


## LTE modem Huawei B2338 - 168 - Wi-Fi indicators are not lit




- If the Wi-Fi indicators are not lit, it may not be a serious problem.
- First, we verify that the router is working properly and that the system and LTE indicators are lit.





• The quickest solution to verify the functionality of the Wi-Fi adapter is a factory reset, as all Vodafone modems have the Wi-Fi adapter turned on in the factory settings.







## The troubleshooting procedure did not help?



- If even a reset does not help to solve the problem, you need to contact the technical support department by calling us or using the Tobi chatbot on our website www.vodafone.cz.
- Only a service technician authorized by Vodafone can replace the router or antenna (manipulate it).